

VOLVO

25.3.57.

CARS AND VANS

Group 351 No.A5

CLUTCH CONTROL

PV 444

Service Bulletin.

Only for Volvo Dealers Service Bulletin file.

Re: Clutch pedal free play.

From chassis No. 131918 onwards, a spring-loaded push rod has been incorporated in the clutch control system. The result of this is that if the clutch pedal free play is adjusted in accordance with the earlier specification (20-25 mm), it is not always certain that the clutch will disengage completely. We recommend, therefore, that you adjust the clutch until it disengages completely taking care to ensure, however, that clutch free play does not disappear altogether.