

VOLVO Cancels earlier bulletin of November 11, 1957
December 5, 1957

Group 450 No. A100

PROPELLER SHAFT

P 44408 USA

Service Bulletin.

Only for Volvo Dealers Service Bulletin file.

Universal joints, type "Sealed for life"

We are introducing the above type propeller shafts on 4000 P 44408 cars. These are not provided with grease nipples so that the universal joints do not require greasing when all-round lubrication is carried out. These have been introduced on chassis numbers 151123-163552.

In the event of customers complaining about the lubricating points being missing, they should be informed of this bulletin.

Details of part numbers are as follows:

	<u>Earlier production</u>	<u>Later production</u>
	With grease nipple	Without grease nipple
Front propeller shaft	89854	656826
Rear propeller shaft	89460	656827
Center bearing flange	86460	656828

The front shafts, part nos 89854 and 656826 respectively, are directly interchangeable with each other. The rear propeller shafts, part nos 89460 and 656827 respectively, are interchangeable if the respective flanges, part nos 86460 and 656828, are also changed at the same time.