

VOLVO

November 1959

Cars PV 544

Group 835 NoA 100

REAR VENTILATION
WINDOW

PV 544

Service Bulletin.

Only for Volvo Dealers Service Bulletin file.

Regarding rattling of rear ventilation window

In order to avoid complaints of rattling from the rear ventilation windows, a spring washer can be inserted between the lock handle and the joining piece (the part attached to the ventilation window frame). The lock handle must be milled down to accommodate the washer.

The above spring washer is now included in our production.

If there should be any difficulty in carrying out this work, the whole lock can be replaced.

Lock, complete, left	657747
Lock, complete, right	657748
Locking washer, spring	90980
Rivet	657750