

VOLVO

October 1959

Group 885 No. A100

Service Bulletin.

HEADLINING MATERIAL

P 544 P 1200

Only for Volvo Dealers Service Bulletin file.

Headlining material P 544, P 1200

Some cases have occurred where the headlining material has been damaged by the sealing compound for the windscreen and rear window which has meant that the headlining has had to be replaced.

The sealing compound in question has been used on the following vehicles:

P 544	chassis nos.	232592 - 240234
P 1200	" "	20252 - 27854

When replacing the headlining, the windscreen and rear window should be removed and the body and rubber sealing strips carefully cleaned before the new headlining is fitted.