

## Service Bulletin.

TIE ROD AND  
STEERING RODS

PV 444 - 445

New model tie rod and steering rods for PV 444 - 445

On the above-mentioned vehicles, tie-rods and steering rods with ball joints that can be lubricated. These modifications have been introduced into production as follows :

P 444	Chassis No. 192842
P 44501	" " 3786
P 44505	" " 4032
P 44506	" " 11716
P 44507	" " 7751
P 44508	" " 7753

The ball joints on the new steering rods should be lubricated through the nipples at the same intervals as the front suspension, i.e. every 1250 km (750 miles). The new parts, which are fully interchangeable with the previously used parts and which have been earlier used on PV 444-445, have the following part numbers:

89221	Steering rod, complete, left
89222	Steering rod, complete, right
89223	Tie rod, complete
89410	Ball joint for tie rod, left-hand thread
89411	Ball joint for tie rod, right-hand thread