

Service Bulletin

Only for Volvo Dealers Service Bulletin file.

STEERING ROD
PV 445, PV 544

Outer grease nipple on steering rod, PV 445 and PV 544

In order to obtain larger clearance between the steering rod grease nipple and the brake drum, we are now fitting a grease nipple without an elbow section on the above-mentioned vehicles. This modification was introduced into production as follows:

P 5440	from chassis no. 200387 onwards
P 44505	" " " 4412 "
P 44506	" " " 12326 "
P 44507	" " " 9067 "
P 44508	" " " 3811 "

If cases are encountered where the grease nipple or the angle section come into contact with the brake drum or in other cases where the grease nipple is to be replaced, we recommend you to remove the elbow section and instead fit a grease nipple AH 1/4" -- 28 SAE-LT, part number 951739. It may be possible to use the nipple that was earlier on the elbow section.