

VOLVO

November 1959

Group 1052 No. A 15

Service Bulletin.

SAFETY BELT

Only for Volvo Dealers Service Bulletin file.Concerning safety belt 279747

In order to prevent the safety belt from slipping out of its adjusted position, the spring in the locking shackle should, where necessary, be adjusted with a pair of pliers as shown in the diagram. The spring should be squeezed together so much that the belt is gripped by the lock.

