

VOLVO

Group 278 No. A100

Service Bulletin.

A I R F I L T E R S

P 1900, P 44408

Only for Volvo Dealers Service Bulletin file.

Air filters, B14A engine.

When both the air filters have been removed from the carburetters and are to be re-fitted, make sure that the gaskets and the air filters are fitted correctly. In each carburetter there is an air channel through which air from the filter is taken to the suction chamber unit on the carburetter. There is not so much risk of the gaskets being incorrectly fitted since they have the same profile as the surface of the carburetter housing. In order to ensure that the air filters are correctly fitted, check that the hole in the filter indexes with the hole in the carburetter. See the illustration below.

A I R F I L T E R

