

VOLVO

October 1959

Group 350 No. A100

Service Bulletin.

CLUTCH PLATE

B 16 A and B 16 B

Only for Volvo Dealers Service Bulletin file.

We have introduced in production a new clutch plate with modified hub design.
The new clutch plate has been introduced as follows:

P 544	engine type	B 16 A	engine number	106961
P 544	"	"	B 16 B	" " 52832
P 1200	"	"	B 16 B	" " 54241

The new clutch plate has part number 659699.

Concerning P 1200 with B 16 A engine, a new type of clutch has been introduced,
see Service Bulletin Group 350 No. A 16.