

VOLVO

June 1959

CARS

Group 58 **No.** A100

Service Bulletin.

TRACK ROD,
REAR SUSPENSION
121, 122S

Only for Volvo Dealers Service Bulletin file.

Should the track rod bracket break, it can be replaced by the bracket with part no. 653202 which is bolted and welded onto the car.

The bracket is attached as follows:

1. Remove the old track rod bracket.
2. Locate the new bracket accurately in the place of the old one. Then drill eight holes and bolt the bracket into position with the help of the reinforcement washers 660624, bolts 921841 and nuts 950394.
3. Adjust the track rod bracket and weld it to the longitudinal member at the point marked X in the illustration.

The repair kit does not fit cars with a chassis no. lower than 2611.

