

VOLVO

October 5th, 1957

Cancels previous bulletin Group 600 No. A100 dated September 9th, 1957

Group 600 No. A100

Exhaust Pipe

P 4440, P 44408,
P 44501, P 44505,
P 44506, P 44507,
P 44508

Service Bulletin.

Only for Volvo Dealers Service Bulletin file.

Nuts for front exhaust pipe on B16 engines

Due to complaints of leakage and deformation of the nuts, the earlier type brass nuts have been replaced by stainless steel ones. Part numbers of the earlier nuts and the new ones are in accordance with the following table:

Earlier nuts

150177

New nuts

190852

The new nuts have been introduced with effect from the following chassis numbers:

P 4440-08	-	149281 onwards
P 44501	-	3646 "
P 44505	-	2670 "
P 44506	-	9037 "
P 44507-08	-	4062 "

The new nuts can be ordered from our Spare Parts Department.

Printed in Sweden