

VOLVO

April 21st, 1959

Service Bulletin.

Group²⁷⁷ No. 100

OIL FILTER

B16A and B16B engines

Mann & Hummel oil filters

Please note that the retainer 418004 and the packing 418005 are not included in the element replacement pack.

Both these parts should be retained when replacement is carried out and should not be thrown away.

See numbers 6 and 7 on page 13 in the P 54408 Spare Parts Catalogue.