

VOLVO

February 1960

Cars

Group 875 No.A4

WINDSCREEN WIPER

P 1200

Service Bulletin.

Only for Volvo Dealers Service Bulletin file.

Concerning SWF windscreen wipers

Windscreen wipers of SWF manufacture have for some time been fitted to certain serie of P 1200. Both wiper units with Auto-Lite motor and complete units from SWF (with motor) will in future occur in our production. The complete wiper units are directly interchangeable.